

SATELLITE DAMAGE ASSESSMENT FOR POTI, GEORGIA

This overview map presents a satellite-based damage assessment for the port city of Poti, Georgia following the armed conflict between Georgian and Russian military forces in August 2008. Damaged vessels have been identified with QuickBird satellite imagery acquired on 25 August 2008 at a spatial resolution of 60cm. A total of 6 Georgian naval vessels within the mapped extent of Poti have been identified as either partially or completely submerged in the Gavan Novyy section of the port. No other damage to physical infrastructure or vessel-related oil spills were detected. Please note, this is an initial damage assessment and not all damage sites have been independently verified on the ground. Please send additions/corrections to UNOSAT.

Damage Assessment with QuickBird on 25 August 2008

Satellite Data QuickBird
Resolution 60 cm
Imagery Date 25 August 2008
Copyright Digital Globe (2008)
GIS Data USGS, UNEP, UNOSAT
Damage Analysis UNOSAT 2008
Map Production UNOSAT 2008
Projection Pulkovo 1995 GK Zone 8N
Datum Pulkovo 1995

The depiction and use of boundaries, geographic names and related data shown here are not warranted to be error-free nor do they imply official endorsement or acceptance by the United Nations. This map was produced by the United Nations Institute for Training and Research (UNITAR) Operational Satellite Applications Program (UNOSAT). UNOSAT provides satellite imagery & related geographic information to UN humanitarian & development agencies & their implementing partners.

